



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCPA41F097998	Model Year 2001	License # 201	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCSA2VF074992	Model Year 1997	License # 56	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAKB7A2TF069003	Model Year 1996	License # 70	Rated Capacity ***** 78
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAKB7A4TF069004	Model Year 1996	License # 87	Rated Capacity ***** 78
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAKB7A5VF074991	Model Year 1997	License # 51	Rated Capacity ***** 36
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAKB7A6TF069005	Model Year 1996	License # 104	Rated Capacity ***** 78
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAKCFA8SF062496	Model Year 1995	License # 100	Rated Capacity ***** 78
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANB7A1RF062494	Model Year 1994	License # 263	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANB7A3RF062495	Model Year 1994	License # 264	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANB7A6XF087310	Model Year 1999	License # 313	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANB7A8XF087311	Model Year 1999	License # 311	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANB7AXXF087312	Model Year 1999	License # 312	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAGGBXA54F217460	Model Year 2004	License # 100	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAGGBXA74F217461	Model Year 2004	License # 5	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMB7A0VF74993	Model Year 1997	License # 64	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMB7A1WF080061	Model Year 1998	License # 7	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMB7A3PF055812	Model Year 1993	License # 133	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMB7A6NF051623	Model Year 1992	License # 38-3	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMB7AXWF080060	Model Year 1998	License # 8	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMBXA62F204302	Model Year 2002	License # 348	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABMC7A6WF080059	Model Year 1998	License # 150	Rated Capacity ***** 90
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABN8XA93F210628	Model Year 2003	License # 37	Rated Capacity ***** 84
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBKA34F217891	Model Year 2004	License # 263	Rated Capacity ***** 81
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBKA54F217892	Model Year 2004	License # 264	Rated Capacity ***** 81
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBKA95F227679	Model Year 2005	License # 149	Rated Capacity ***** 42
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBXA03F210629	Model Year 2003	License # 6	Rated Capacity ***** 84
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBXA11F097996	Model Year 2001	License # 202	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAHB7A5PF055813	Model Year 1993	License # 38-5	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBHG35K2PF355127	Model Year 1993	License # 101	Rated Capacity ***** 16
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBJ6PIP7MV101489	Model Year 1991	License # 231	Rated Capacity ***** 22
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBM7T1C21J511944	Model Year 2002	License # 238	Rated Capacity ***** 48
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBM7T1C21J512365	Model Year 2002	License # 237	Rated Capacity ***** 48
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GDM7T1J6PJ516787	Model Year 1993	License # 91	Rated Capacity ***** 48
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Browning Public Schools	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX0061	Model Year 1998	License # 387	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Other	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAGCSH1TF068470	Model Year 1996	License # 92	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAGCSH8VF073233	Model Year 1997	License # 286	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCPH42F202487	Model Year 2002	License # 132	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCPH43F211062	Model Year 2003	License # 211	Rated Capacity ***** 64
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCPH4YF090864	Model Year 2000	License # 58	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCPH61F097997	Model Year 2001	License # 26	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCSH1XF084610	Model Year 1999	License # 85	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCSH4WF078105	Model Year 1998	License # 299	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABHCKH15F225130	Model Year 2005	License # 395	Rated Capacity ***** 62
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPB70K3JVA43945	Model Year 1988	License # 181	Rated Capacity ***** 66
Chassis Make Ford	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 18 Glacier		District Name Cut Bank Public Schools	
Vehicle I.D. # (VIN) - Entire Number 2GBHG31M064152339	Model Year 1982	License # 55	Rated Capacity ***** 21
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date